



Cascade shown fully assembled for illustration purposes.

Installing the mounting bracket





Use the mounting bracket to mark the fixing hole positions on the underside of the work surface.




With a suitable tool, drill 2x 3mm pilot holes on the positions marked on the underside of the work surface.

Contents




Use the 2x supplied fixing screws to fix the mounting bracket to the underside of the work surface as shown.

Installing the weighted base




Orient the base to suit the cable entry as desired and offer up to the bottom connecting block (a). Push the bottom connecting block onto the base until it clicks into place (b).

Cable management



Carefully push the cable through the gaps in the corners of the connecting blocks. Bend the cable as shown to make insertion easier.



Repeat until the cable is fully contained in the product. Repeat steps 5-6 for any additional cables. It is advised to keep power and data separate.

Additional information

Safety

- Ensure the screws used for installation are suited to the furniture material. Contact your furniture supplier for a recommendation if necessary.
- Installation is to be carried out in accordance with relevant Health & Safety regulations and only to be carried out by a skilled or competent person.
- Product to be used only for the intended purpose of supporting power and data cables in office and commercial environments.
- Do not misuse the product because doing so will invalidate the warranty.

Product care

- Clean using a dry cloth. No abrasives or solvents to be used on the product.
- Do not drop or expose to moisture.

